

C. Poivey¹, H. Kim¹, C. Seidleck¹, K. LaBel²
J. Karsh², S. Pursley², I. Kleyner², R. Katz²,
S. Pursley²

¹ MEI Technologies ² NASA - GSFC


To be presented by Christian Polivey at the 2006 Single Event Effects Symposium (SEESYM), April 10, 2006 to April 12, 2008 in Long Beach, CA



Outline

- Background Introduction
- Summary of recent test results
 - RHLP4913
 - MSK5900
- Conclusion

To be presented by Christian Polivey at the 2006 Single Event Effects Symposium (SEESYM), April 10, 2006 to April 12, 2006 in Long Beach, CA.








Background


- SET in voltage regulators are a concern for low voltage applications (< 5V)
 - Overvoltages may cause destructive conditions
 - Undervoltages may cause functional interrupts
- SET in voltage regulators are critical for FPGA RTAX
 - DC core absolute max rating = 1.6V
 - 1.5V core supply voltage recommended operating conditions: 1.425V min, 1.575V max


To be presented by Christian Poivey at the 2006 Single Event Effects Symposium (SEESYM), April 10, 2006 to April 12, 2006 in Long Beach, CA.





























NASA

Conclusion

- SET sensitivity changes significantly from type to type
- Worst case bias is different from type to type
- Adding up output capacitors is not always effective
- Filtering does not remove all SETs
- Filtering methods without resistor elements proved to be effective

To be presented by Christian Policey at the 2006 Single Event Effects Symposium (SEESYM) April 10, 2006 to April 12, 2006 in Long Beach, CA